US ERA ARCHIVE DOCUMENT

LIN	LIMITLOC		me	2. Date Prepared	3. Time Prepared
UNIT LOG		Kalama	zoo River/Enbridge Oil Spill	09/27/2012	1600
4. Unit Name/Designators 5. U		5. Unit Leader	5. Unit Leader (Name and Position)		6. Operational Period
Situation Unit		Melinda Luetke, Planning Section Chief		0700, 09/27/12 –	
					0700, 10/04/12
7.			Personnel Ros	ter Assigned	
Name			ICS Position		Home Base
Larry Rader		Situation Unit Leader		Chicago, Illinois	
8.			Activity Log		
Time	Major Events				
0930	Boat safety briefing at C0.4 boat launch. Launch.				
	Operational status:				
	Observed sheen and tar globules within containment at control point above Ceresco Dam.				
	 Observed crews removing vegetation and debris from containment boom above Ceresco Dam. 				
	Observed boat-agitated sheen in southwest corner of Ceresco Dam along LDB.				
	Observed sheen along impoundment on south side of Ceresco Dam.				
	· Inspected Island F, no sheen observed.				
	• Observed sheen and tar globules at MP 15.50 (north end of south Mill Pond) RDB following agitation if sediment by boat.				
	 MP 15.75- No sheen observed at north end of Mill Ponds. 				
	 Observed sediment trap at MP 36.1 RDB, no sheen observed. Some debris observed behind sediment trap structure. 				
	 Observed boom and curtain inspection crew working along boom in southwest corner of Morrow Lake Delta. 				
	· No sh	een obser	ved in Northern or Southern	n coves of Morrow	Lake.
	Additional observations: None				
1520	Return to ICP.				

Larry Rader, Situation Unit Leader, USEPA-START